



Model: LO45-20BxxSMU-C-zzz, LO45-20BxxSMU-zzz, LO45-20BxxMU-C-zzz, LO45-

20BxxMU-zzz

LO65-20BxxSMU-C-zzz, LO65-20BxxSMU-zzz, LO65-20BxxMU-C-zzz, LO65-

20BxxMU-zzz

Manufacturing Mornsun (HuaiHua) Science & Technology Co Ltd

Facility(ies): No.16, Jianshe Avenue High-tech Industrial Development District

Huaihua, Hunan 41800 China

Applicant: MORNSUN GUANGZHOU SCIENCE & TECHNOLOGY., LTD.

No.8, Nanyun Road 4, Huangpu District, Guangzhou

Guangdong

Guangzhou, 510670 China

E347375

Listee: Same as Applicant

Listee File No.:

Report No.: E347375-D1007-1/A0/C0

Report (Re)Issue

Date:

2022-01-26

Standard(s): ANSI/AAMI ES60601-1:2005/(R)2012 and A1:2012, C1:2009/(R)2012 and

A2:2010/(R)2012, CSA CAN/CSA-C22.2 NO. 60601-1:14

Additional Standards: None

Report Types: This report consists of the following report types:

[Yes] US Certification (UL Recognition)
[Yes] CAN Certification (cUL Recognition)

You are receiving this report as a Manufacturing Factory for the above-referenced Applicant.

This report covers the Safety evaluation of the referenced model(s) according to the standard(s) specified above.

This report includes portions of the full Applicant report and is designed to support any Follow-Up inspections at the Manufacture's facility.

Please refer to any Supplements to this document for a detailed manufacturer report, which includes information for the Follow-Up Inspection as specified below:

- Appendix C: Follow-Up Service Documentation

- Appendix A: Enclosures

Report Modifications Summary

The following changes were made to this report. If none listed in the below table, this report is the originally issued report.

NOTE: Some of the changes listed below were made in the full report and may not reflect the changes in this associated Factory Report, which just includes the Appendices listed above from the main report.

Date Modified (Year-Month-Day)	Modifications Made (include Report Reference Number)	Modified By
2022-01-26	E347375-D1007-1/A0/C0-UL Original	Joy Lao / Rocky Tan