Safety Warnings for LS Series Power Supply Production

Cautious! High voltage danger!

Production and commissioning staff must be trained before operating.

◆ 1.DO NOT TOUCH! High voltage AC input!

◆ 2.Take protective measure against the high voltage during production and commissioning!

◆ 3.High voltage warning in the field of production and commissioning!

 4. Cautious! Residual high voltage from the external capacitor after power off

High voltage area

DO NO TOUCH! High voltage area (red-framed on the left)

Isolation protection

Please add an isolation transformer(50Hz / 220V) for safe isolation protection during production and commissioning process, except for terminal normal application. Recommended isolation transformer: JMB-500VA

Cautious! Residual high voltage

Cautious! Residual high voltage from the filtering capacitor after commissioning operation! Please use resistor to discharge the capacitor after commissioning, to avoid electric shock by capacitor discharging